G. R. S. 59]

GENERAL AND REVENUE SECRETARIAT.

190

( )

File No. 202-86

Serial Nos.

Papers Filed.

*Month*_____

SUBJECT.

PREVIOUS REFERENCES.	LATER REFERENCES.

OFFICE OF THE DEWAN OF MYSORE
RECEIVED
Date 2-6-93
Reg. No. 1991
EDUCATION

To

Extract from Minutes of
Proceedings of Secretary to the
Government of

Sir,

I am hereby directed to inform
Executive Engineer Kolar Division
for the repairs of the Lake Anicut Kesthi madug
Chattram at Jaralimarahalli the
estimate provides for relinding the parapet
and repairing the front and repairing the bunds
with mangalore tiles. If the stones or other
kinds of wood be used instead of [illegible]
work carried out [illegible] with
contract systems there may be a saving
in the amount of the estimate

only when an inspire

one thousand pieces is stamped on and

the same procured by annually or

yearly bills of the Irish Linen dep.

A Copy of the Act mentioned on

the stamp in the Lake Chairs of

Chatham is also herewith submitted

as desired in person.

I beg to remain

Sir

Your most obt Servt

Thos Bulkeley

Gibraltar

The Roof of Repairing -

Linear Brass Chair in Cheltenham at -

Kiccavathi - Seringapatam -.

Detail of work.	No:	Dimensions.			Quantity.	Rate
		L	B	D		
Main Building -						
Disused Old work in places Linear Brass Rft.						6 £
Clearing Turfy & Levelling Verandah inside & outside					L S	£
1st Floor. — Burnt Bricks in Clay cft.						
Gables to end walls -	2	15'	1/8	5½	8 4	
do in Cross walls inside	2	5'	3/8	5½	8 4	cft.
Levelling between Rafters	2	54	1/8	1	1.29	2 16
Teak wood work cft. -						
Rafters in front Verandah.	1	10	1/4	3/8	0.13	
do - in rear Verandah	20	10	1/2	3/8	18.75	
Breastsummers to do - -	1	58	1/3	1/2	9.40	
Posts -	8	5'	1/2	1/2	10.00	
Braces and Capitals	16	1	5/12	5/12	3.00	
Rafters in Main Hall	20	11	1/2	3/8	20.62	
Shrouds over Beam, in centre	6	6	1/3	1/2	6.00	
do - at sides - -	2 x 6	4	1/3	1/2	8.00	
Ridge piece -	1	59	1/3	1/2	9.83	cft.
Wall Plates -	2	58	1/3	1/2	19 6	102.09
Roofing with Mangalore tiles, and Chunam borders & bands including Teak rafters complete -.						
do. Roof of Main Building both side	1	58	"	22	12[illegible]	[illegible]
do - Rear Verandah - -	1	58	.	9	522	14.76
Mangalore Ridge tiles including Pointing - Rft.						
Ridge of Main Building	1	58	.	"	58	58

Ordinary Cornice — Rft.

to to Nos 26 & 28 on side at ends	2	20				
[illegible]						
[illegible]						
to to rooms	3	3¼	×	6¼	61	
to to	1	2 3/4	×	6	16	
" " 4 ft 2 ll	2	3 4	×	6½	43	
[illegible]	1	2	×	3	13	
[illegible]	1	2	×	3	4	Sft 190

[illegible]

[illegible]

[illegible]

Western wall	1	20	"	10	200	
Brick on edge under 2 layers of flat tiles + Plastering over all	1	58	9	"	522	Sqrs 5.22
Temp: to Pillars and walls Lumpsum (R)				Sqrs		2.00.
Repairing floor Lumpsum (R)						2/=
Teak wood work — Sft. Door Shutter, Battens complete	2	3	.	6	36	3/ 6d
White washing 2 coats: —— Sqrs:						
do — Hall	1	72	.	11	792	
" Room	1	53	"	11	583	
" do	1	54	"	11	594	
Front Verandah	1	50	"	10	500	
Cross walls of do	2	6	"	8	96	
Rear Verandah	1	23	.	10	230	
Cross walls of do	2	7	"	10	140	
Verandah	2	14½	"	10	290	
Cross walls	2×2	7½	.	10	300	
white washing to Ceiling	1	29	"	13	377	Sqrs
do in Room	2	1—	"	12	234	12.10
Repairing wooden Stair Case (Lumpsum) (R)						5/=
Court yard						
Dismantling old stone Lumpsum (R)						2/=
Teak wood work —						
Rafters and Purlins	2	20	½	5¼	15 70	
do in Eave		22	½	2¼	6 60	
Rafters, Couples inside	2×2×2	10	1.	1½	60 60	
do - Tie beam in gables	5×2	0	"	8	5	
do - in gables	2×2	10/2	"	2/2	10	
Purlins and Ridge	2×2	10	1/4	8	20	
Eave board inside & out	21	10	"	10	210	
Rafters in hip roof	4×5	.	"	3/5	3	3/
Hip Rafters	4	15	1.	1½	10.50	10/
Mangalore tiles complete — Sqrs.						
to both side slopes	2×2	30	10		132	"
do — Rear Roof	2	20.2	10	"	210	10 3

	Side ridges . .	2					
	Rear ridge .	1	3	"			
	to Slopes	2	15	'	±		
	Line Sheeting Valley — Rft						
	— to Curve on joints of Hip	2	15	'	"	30	
	Whitewashing 2 coats —						S
	to - for ceiling	1	120	'	10	1200	1200 ft
	Plastering with Chunam —						
	" for 1 Arch " Recess						2.00
	Kitchens East and West						
	Rear Wall on ground floor						5/=
	Burnt Brick in Mud — cft						
	to Arches —	2×2	8	1/8	∠	72	cft.
	" Plain Part of Walls to the Arches —	2×2	22	1/8	1	99	171
	Teak wood work — cft						
	Double Shutters	4	3	1/4	3/8	53	
	Doors —	2×2	4	1/4	3/4	1'	cft.
	Single Shutters	2×2	23	1/4	1/3	8	3'7
	Roofing with Mangalore Tiles & Teak Rafters Complete grs.						5 sqs.
	to to Roofing —	2×2	22	11	'	968	968
	Ridge Tiles — Rft						Rft
	" for the Tile	2	22	-	"	44	44
	Ventilating Tiles	No.					
	to " Tile	1×4		"		8	8
	Teak wood doors —						
	" Wooden Frame for Doors	2	2	'	6	36	Sft.
	Teak Rafters —	1	9	"	2	18	54
	" — " Purlins —						
	Plastering with Chunam. 3 grs. —						
	Rear Wall —	1	55	'	5	290	
	to to	1	10	'	12	120	
	to roof —	1	57	"	12	684	
	to Arch —	1	13	"	8	104	

Cieling to the Western wall	1	20	"	10	200
do- gables	2	10	"	5/2	50
do Here & There Lts. Sqrs.					200 16-48

White washing Sqrs:—

do- inside the Kitchen	1	40	"	10	400
do- for gables	2	14	"	5/2	140
do outside wall	1	40	"	15	600
do- inside the Kitchen	1	35	"	10	350
do- gables	2	11	"	5/2	110
Deplaces Veranda Sqrs:					100 10-30

P.T.O...

K Ameen
M S

Abstract

Of Work — Jno Dale — In the Building Courtyard Kitchen | Fo

						1st Floor		Ground Floor		2nd Floor		3rd Floor	
						2p cost	2p cost	2r cost	2r cost	2r cost	2r cost	2r cost	2r cost
Excavating & filling	Less per cu.						5		5		5		20
Clearing, levelling & grubbing	"	"	"	"		"	"	"	"	"	"	"	5
Brick & Brickwork	cft	"	2	"	296	37	"	"	"	"	141	21	167	558
Teak wood work wrought & teak	"	3	"	"	102	306	71	213	137 28	412	54	172	367.28	1103
Roofing with Burgh slate & teak, complete	Sqr	22	"	"	17 93	396	"	"	15 30	337	9 68	213	42.96	946
Marseilles pan tiles	Rft	"	8		58	29	"	"	132	61	44	22	234	117
Ceiling & partitions with Plastering	"	"	2	"	40	5	"	"	"	"	"	"	40	5
Teak wood doors and windows with Shutters complete	sft	"	10	"	190	119	36	22	"	"	54	34	280	175
Plastering with cheunam	Sqr	2	8	.	6.66	14	2 00	5	2.00	5	16 48	41	27 13	68
Teak wood Railing	Pft	"	8	"	52	26	"	"	"	"	"	"	2	26
White washing 2 coats	Sqr	"	3	"	36 39	"	49 10	8	12 00	2	19 20	4	110.39	21
Repairing floor with cowdung	Lump S					10	"	2	"	"	"		"	12
Terrace with brick on edge & Plastering	Sqr	25	"	"	"	"	5 22	130	"	"	"	"	5.22	130
Repairing wooden Staircase - & S Fo							"	5	"	"	"	"	"	
Iron Valley Sheet	Sft	"	8	"		"	"	"	30	15	"	"	30	15
Ventilating tiles	each	1	"	"		"	"	"	"	"	8	8	8	8
Total Rs		"	"	"	"	"	062	"	370	"	842	"	724	"	2714

Estimate [illegible]

[illegible]